

GRANT UNDER TFC DURING 2006-07

1

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figre in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)
<u>EASTERN ZONE</u>						
<u>BASAR CIRCLE</u>						
Daporijo Division						
1	Repair and maintenance of Circuit House at Daporijo	5.00	5.00	4.74	Being up-loaded, possibly along with photographs.	
Dumporijo Division						
1	Repair and maintenance of Circuit House at Dumporijo	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
Basar Division						
1	Repair and maintenance of Circuit House at Basar	20.00	20.00	28.96	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of IB at Gensi	4.00	4.00		Being up-loaded, possibly along with photographs.	
3	Repair and maintenance of IB at Likabali	5.00	5.00		Being up-loaded, possibly along with photographs.	
Basar Circle		37.00	37.00	36.70		

GRANT UNDER TFC DURING 2006-07

2

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figre in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)
	ALONG CIRCLE					
	Along Division					
1	Repair and maintenance of Circuit House at Along	12.00	12.00	12.00	Being up-loaded, possibly along with photographs.	
	Mechuka Division					
1	Repair and maintenance of IB at Mechuka	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.	
	Yomcha Division					
1	Repair and maintenance of IB at Yomcha.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of Circuit House at Tirbin.	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.	
	Rumgong Division					
1	Repair and maintenance of IB at Rumgong.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
	Along Circle	28.00	28.00	28.00		

GRANT UNDER TFC DURING 2006-07

3

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figre in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)

BOLENG CIRCLE**Boleng Division**

1	Repair and maintenace of Circuit House at Boleng	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.
---	--	------	------	------	---

Pasighat Division

1	Repair and maintenace of Circuit House at Pasighat.	7.00	7.00	7.00	Being up-loaded, possibly along with photographs.
---	---	------	------	------	---

2	Repair and maintenace of Siang Guest House (Annexe) at Pasighat.	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.
---	--	------	------	------	---

3	Repair and maintenace of IB at Mebo.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.
---	--------------------------------------	------	------	------	---

4	Repair and maintenace of Siang Guest House at Pasighat.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.
---	---	------	------	------	---

Boleng Division

1	Repair and maintenace of IB at Pangin.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.
---	--	------	------	------	---

2	Repair and maintenace of IB at Yambang.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.
---	---	------	------	------	---

GRANT UNDER TFC DURING 2006-07

4

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figre in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)
Yingkiong Division						
1	Repair and maintenace of Circuit House at Tuting.	5.00	5.00	20.49	Being up-loaded, possibly along with photographs.	
2	Repair and maintenace of Circuit House at Yingkiong.	9.50	9.50		Being up-loaded, possibly along with photographs.	
3	Repair and maintenace of Circuit House at Jenging.	6.00	6.00		Being up-loaded, possibly along with photographs.	
Mariyang Division						
1	Renovation & extension of IB at Katan.	5.00	5.00	4.97	Being up-loaded, possibly along with photographs.	
Boleng Circle		54.50	54.50	54.46		

GRANT UNDER TFC DURING 2006-07

5

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figure in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)

TEZU CIRCLE**Tezu Division**

1	Repair and maintenance of Circuit House at Tezu.	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of IB at Sunpura.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	

Namsai Division

1	Repair and maintenance of Circuit House at Namsai.	4.00	4.00	4.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of Circuit House at Wakro.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	

Hayuliang Division

1	Repair and maintenance of IB at Hayuliang.	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.	Booked in Part-V
2	Repair and extension of Guest House at Wallong.	30.00	30.00	30.00	Being up-loaded, possibly along with photographs.	Booked in Part-V

GRANT UNDER TFC DURING 2006-07

6

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figre in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)
Roing Division						
1	Repair and maintenance of Circuit House at Roing.	4.00	4.00	4.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of IB at Hunli.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
3	Repair and maintenance of IB at Desali.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
4	Repair and maintenance of IB at Dambuk.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
5	Repair and maintenance of IB at Paglam.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
6	Repair and maintenance of IB at Bomjir.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
7	Repair and maintenance of IB at Dholla.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
Anini Division						
1	Repair and maintenance of CH at Anini.	4.00	4.00	4.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of IB at Italian.	4.00	4.00	4.00	Being up-loaded, possibly along with photographs.	
Tezu Circle		80.00	80.00	80.00		

GRANT UNDER TFC DURING 2006-07

7

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figure in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)
JAIRAMPUR CIRCLE						
Changlang Division						
1	Repair and maintenance of CH at Mohan-bari.	9.00	9.00	9.00	Being up-loaded, possibly along with photographs.	
Khonsa Division						
1	Repair and maintenance of CH at Khonsa.	4.00	4.00	4.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of CH at Deomali.	3.00	3.00	3.00	Being up-loaded, possibly along with photographs.	
Longding Division						
1	Repair and maintenance of CH at Longding.	4.00	4.00	3.79	Being up-loaded, possibly along with photographs.	
Jairampur Division						
1	Repair and maintenance of CH at Jairampur.	5.00	5.00	5.00	Being up-loaded, possibly along with photographs.	
2	Repair and maintenance of CH at Miao.	4.00	4.00	4.00	Being up-loaded, possibly along with photographs.	
Jairampur Circle		29.00	29.00	28.79		
Grand Total (A)		228.50	228.50	227.95		

GRANT UNDER TFC DURING 2006-07

8

Sl. No	Name of Work	Estimated cost	TFC Grant during 06-07	Expenditure incurred during 06-07	Physical Progress as on date	Remarks
			(Figre in lakh)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)
Earmarked Schemes						
BOLENG CIRCLE						
Pasighat Division						
1	Maintenance of log bridges at river Kadang Krong, Ngopok Krong, Taksing Krong, Seram Krong and Tara Tamak on Mebo Dholla road.	17.45	17.45	17.45	Being up-loaded, possibly along with photographs.	
BASAR CIRCLE						
Basar Division						
1	Improvement of Litemor-Tara Mori PWD Road.	47.00	47.00	47.01	Being up-loaded, possibly along with photographs.	
Earmarked schemes (B)		64.45	64.45	64.46		
Grand Total (A+B)		292.95	292.95	292.41		